

M12 Triaxial Accelerometer Wiring

The triaxial accelerometers offer three axes of measurement in one accelerometer package.




Figure #1 – M12 Triaxial Wiring Diagram

As shown in Figure #1, the 4 pin output includes:

- Pin 1 = Axis Y (Integral cable color = red)
- Pin 2 = Axis X (Integral cable color = green)
- Pin 3 = Axis Z (Integral cable color = white)
- Pin 4 = Common (Integral cable color = black)

[Click here](#) to download our entire guide to wiring CTC accelerometers.

