

CSI Adapters: CMX2100 Series

CMX2137-V

Single Channel Voltage Input

Reverse keyed 5 Pin M12 to BNC "E" jack, adapter for voltage input.

For CSI 2130 only.



CMX2138

Single Channel Acceleration

5 Pin M12 to BNC "E" jack connector, adapter for single channel acceleration input.

For CSI 2130/2140.



CMX2139A

Triaxial Acceleration

Black polyurethane cable, 6ft., with 5 socket dual key connector for CSI A0643TX triax, to 5 pin M12 connector, Triax acceleration input.

For CSI 2130/2140 only.



CMX2139A-SFT

Triaxial Acceleration with Safety Feature

Black polyurethane cable, 6 ft., with 5 socket dual key connection for CSI A0643TX triax, to 5 pin M12 connector, for Triax acceleration input. Includes safety feature .

For CSI 2130/2140 only.



CMX2147

Tachometer Input

8 Pin M12 Connector to 4 Pin Lemo Connector. 22 inch (56 cm) length.

For CSI 2140 with CSI SpeedVue™ Sensor.



CMX2148

Tachometer Input

8 Pin M12 Connector to 4 Pin AMP Connector. 2 foot (61 cm) length.

For CSI 2140 with 404 Series Laser Tach.

