


Junction Box Mounting Kits




BOXMOUNT-1A




Four (4) MH153-1A Magnets and four (4) MH108-48B M5 Panhead Screws

BOXMOUNT-1B




Four (4) MH153-1A Magnets and four (4) MH108-47B M5 Panhead Screws

BOXMOUNT-2A



Four (4) MH114-3A Magnets and four (4) MH108-45B 1/4-28 Panhead Screws

BOXMOUNT-3A



Four (4) MH115-2A Magnets and four (4) MH108-45B 1/4-28 Panhead Screws